

Cleaning Instructions

WeatherMax Fabrics may be spot washed by using a soapy solution of a mild detergent and lukewarm water. Rinse thoroughly with clean water to remove soap and allow to air dry. For mildew stains prepare a solution of 1 cup bleach plus ½ cup mild detergent per gallon of water. Spray on the entire area and allow soaking. Rinse with clean water and allow to air dry.